

NO RECORD



Y-228



Bearings are based on an assumed meridian and are intended to be used for angular determination only.

LEGEND

● IRON PIN FOUND



NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE

Initial: MLB Date: 8-10-07

SURVEY BY: Douglas C. Seiler
DOUGLAS C. SEILER PS. #6869
for SEILER & CRAIG SURVEYING INC.
52-1/2 NORTH MAIN STREET
MANSFIELD, OHIO 44902
(419) 525-3643
FAX (419) 525-3696

SURVEY PLAT FOR
JAMES J. GOLDSMITH
PART OF LOT #10141
CITY OF MANSFIELD
OHIO
Date: August 3, 2007 Scale: 1" = 40'
522hartr.dwg/566hartr.asc

SEILER & CRAIG SURVEYING, INC.

Douglas C. Seiler, PS & Chad F. Craig, PS

52 1/2 North Main Street

Mansfield, Ohio 44902

419-525-3644 Fax 419-525-3696

www.seilerandcraig.com

SURVEY DESCRIPTION

PART OF LOT #10141
CITY OF MANSFIELD, OHIO

Situated in the City of Mansfield, County of Richland, State of Ohio and being a part of Lot #10141 of the consecutively numbered lots in said city, and being more particularly described as follows:

Commencing at an iron pin found and accepted as marking the northeast corner of Lot #10142 in said city; Thence, North 01 degree 00 minutes 00 seconds East with the west line of Harter Avenue, a distance of 164.38 feet to an iron pin found, said iron pin being the place of beginning of the parcel herein described;

Thence, continuing North 01 degree 00 minutes 00 seconds East with said west line, a distance of 49.91 feet to an iron pin found;

Thence, North 88 degrees 31 minutes 12 seconds West a distance of 199.79 feet to an iron pin found on the west line of said Lot #10141;

Thence, South 01 degree 20 minutes 04 seconds West with said west line, a distance of 50.00 feet to an iron pin found;


Thence, South 88 degrees 32 minutes 47 seconds East a distance of 200.08 feet to the place of beginning, containing 9987 square feet, according to survey by Douglas C. Seiler, Professional Surveyor #6869, on August 3, 2007.

Iron pins set are 5/8" rods with caps stamped "SEILER AND CRAIG INC."

Bearings are based on an assumed meridian and are intended to be used for angular determination only.

NEW SURVEY
OF EXISTING PARCEL
RICHLAND COUNTY
TAX MAP OFFICE

MLC INITIAL 8-10-07 DATE



Douglas C. Seiler
Douglas C. Seiler, Professional Surveyor #6869
for Seiler & Craig Surveying, Inc.