




Revised and recertified

HOCKADEN-LIPES-ROUSCUP, INC.

By *Robert B. Rousculp* 6-16-69
Registered Surveyor

Revised and recertified

HOCKADEN-LIPES-ROUSCUP, INC.

By *Robert B. Rousculp* 6-16-69
Registered Surveyor


Revised and recertified

HOCKADEN-LIPES-ROUSCUP, INC.

By *Robert B. Rousculp* 6-16-69
Registered Surveyor

We hereby certify that we have
above properly and that the official record is correct.

HOCKADEN-LIPES-ROUSCUP, INC.
By *Robert B. Rousculp* 6-16-69
Registered Surveyor



BENCH MARKS

- BM 11: Spike in utility pole on South side line
N.E. of oppon center of property. E1. 46.47
- BM 13: Spike in Power Pole of SE corner of property.
E1. 73.41
- BM 16: Spike in Utility Pole 15 ft. South of NW corner.
on west property line. E1. 72.44

TYPE OF DRAWING		ARCHITECT'S SURVEY	
CHELSEA SQUARE			
MANFIELD, OHIO			
SCALE: 1"=40'		FOR AMERICAN UTILITY PROPERTIES	
DRAWN: E. G. C.	CHECKED: E. G. C.	REVISION: 3-1-69	3-28-69
HOCKADEN-LIPES-ROUSCUP, INC. CONSULTING ENGINEERS 2607 N. NORTH HIGH ST. COLUMBUS, OHIO		SHEET NO. 46 ORDER NO. 10351	